0 8 6 6 - W S 02. 86 64-22/NTA2

> WPF 1/31/86 Page 1 of 13

Work Plan No. Q2-804-22-W1
Revision

NUS CORPORATION WORK PLAN FOR THE

Preliminary Assessment
Midlynd Processing

Located in

Pomona, N. Y. Rockland Courty

Prepared by

Region II

Raritan Plaza III Fieldcrest Avenue Edison, New Jersey 08837

Preparer:	Jeff Josephson
Date:	05/02/86
Review and Approval:	Rulest L. St. QA Representative
Date:	05/66/P6
Review and Approval:	B Taylor L
Date:	Ragional Project Manager

PROJECT SUMMARY

TDD No.: 02-8604-22 US EPA Site No.: NYO 04483708
Site/Project Name: Midland Processing
Location: Pomone, W.Y Rockland Country
NUS/FIT Project Manager: Ron Naman
EPA Site Manager/Contact: Diana Messina
State Site Manager/Contact: Charles Goddand
Date TDD Opened: 05/61/86 Date of Completion: 05/31/86
Estimated Technical Hours: SS Estimated Subcontract Cost: N/A
Account No. 0400.01, TDD Priority (/): High, X Medium, Low
Summary of Assignment (Attach copy of TDD as Attachment A):
See attached TDD
This work plan encompasses TOD specific elements 2 ad 3
2 ad 3
Attach And Reference Additional Sheets If Necessary

	WPF 1/31/86
	Page 3 of 13
Work Plan N	0.02-8604-22 -WI
Revision	0

PROJECT SUMMARY (cont'd)

Deliverable/Fig	al Product to EPA (e.g. reports, etc):
Four page	Preliminary Assessment (PA) Report
(Includes	EPA Form 2070-12 and supporting documentation)
•	
Deliverable/Fir	al Product Review Process:
Review Scope (
x	Review for conformance to project control documents. (ie. the TDD and this workplan).
X	Review for technical and editorial content.
Required Revie	w and Approvals (/):
X	Technical Supervisor
X	Review Committee, If applicable list names or disciplines.
	A qualified reviewer not invloved with deliverable preparation
	will be selected.
X	QA Representative
X	Regional Project Manager or designee (ie. ARPM)
Site History/De	scription:
Prepare brief de past data assess	escription of the site (landfill, drum storage, etc.), conclusions from ments, and indicate the current or past operators.
	lnknown
·	
	· ·

	WPF 1/31/86
	Page 4 of 13
Work Plan No.	Ox-8604-22 -W1
Revision	0

PROJECT OVERVIEW

A11 F	P.A. activities wil	l be conducted in	accordance with NUS Operating
Guide	elines Manual secti	on 4.15 "Prelimin	nary Assessments", Draft 2, 7-16-84
		· · · · · · · · · · · · · · · · · · ·	
	Attach and	Reference Add	itional Sheets If Necessary
Personnel	Assignments:		•
List person	nnel assignment(s	s) for each TDD	task or specific element.
TDD Specific	Required	Number of Persons	
Element	Discipline(s)	Required	Responsibilities/Duties
· 1	Any	1	Project Manager (PM) - Responsible for locating
	-		and assembling all relevant background information
1	Ann	1	Assistant to PM in obtaining and assembling
			relevant background information.
	·		
2	_Any_	1	PM - Responsible for review and evaluation of
·			relevant background information necessary to
			develope PA Report. Additionally will plan and
			conduct off-site reconnaissance if necessary.
	· ·		
		·	
D	Any	1	Assistant to PM - Responsible for documentation

Work	Plan	No.02-8604-22-H1

Revision	0

Personnel Assignments (Cont'd)

TDD Specific Element	Required Discipline(s)	Number of Persons Required	Responsibilities/Duties		
3	Any	1	P.M Responsible for preparation review and		
·		· 	approval of 4-page PA Report. Must ensure		
			all required reviews are performed and documented		
		******	before final approval and submitted to EPA.		
			· .		
					
	_				
					
			·		
					
					
					
	-				
- 					
••					

Schedule of Activities:
Check off as appropriate.
See copy of TDD provided as attachment A.
See attachment A-1
Referenced Background Data:
List background reference material (Usually provided by US EPA).
Identified on U.S. EPA REST CERCLA LIST
Attach And Reference Additional Sheets If Necessary
Safety and Health Considerations:
Refer to the attachment B, the site safety plan which has been approved by the Regional Safety Officer and RPM.
Ref#:03-8604-22 -S1 Date: Safety Officer Approval Date)

	WPF 1/31/86
	Page 7 of 13
Work Plan No.	02-8604-22 -W1
Revision	U

ESTIMATED COST ASSOCIATED WITH ANALYTICAL SUPPORT

N/A

Type of Analysis	Unit Cost(\$)*	No. of Samples	Total Analysis Costs(\$)
-			
-	•		-
			
			<u> </u>
			
			
			<u> </u>
			i.
	· ·	·.	
	-		
	Total Cost of all Ar	nalysis Requested:	

Reference and attach additional pages if necessary.
*If required, include Special Analytical Services (SAS) cost estimates.

	WPF 1/31/86
	Page 8 of 13
Work Plan No.	-02-8604-22-WI
Revision	0

Required Resource List (For equipment, list major items only):

Reference to attached list is acceptable

<u>Item</u>	When Needed	Required Use *
Cameras	When Needed Day of off- site recon.	Photograph documentation
	<u> </u>	
·		

^{*} If measuring or test equipment is needed, indicate whether its required use is for health and safety screening or for evidentiary data collection.

interface/ Planning Requi	rements (Rei	ierence attachi	nents if neces	sary):	• •
Interface with EPA:	FIT RPO, Dia	na Messina (201)	321-6776		
			·		
·					
					
					
Indonésia widh Sanda /I					
Interface with State/Loc	•	Background Fi	le Searches to	be conducted a	t State
Offices.					
	····	· · · · · · · · · · · · · · · · · · ·		:	
					
					
Site Access Arrangement	s (site contac	ct, etc.):			
		/A			
·	- 				
			·		
				•	1
Community Relations Pla				· · ·	
interface with media con					ities
associated with this site	will be referre	ed to EPA.			
					
	- 				
Training Requirements:	N/A	· .			

RECORDS AND DOCUMENTATION

Check off records and documents that will support the validity and evidentiary value technical work conducted and environmental data collected.

<u> </u>	TDD/AOC		Correspondence (Telecon		
<u> </u>	Work Plan		notes, memos, letters, etc.)		
X	Safety Plan	X	Deliverables to EPA (List below)		
<u> </u>	Work Plan/Safety Plan	· .			
	Distribution Documentation	4 Page P.	A. Report		
<u></u>	Calibration and maintenance records for measuring and test equipment (for HNu, OVA etc.)	x	Records of Review and		
	Written Documentation of Field activities (ie Log books notes, calculations etc.)	X	approvals for project control documents and deliverables		
	Photographic Documentation of Field activities		Q.A. records log		
	Soil Stratigraphic Records (drilling logs etc.)		· .		
Procurem	nent Documents (Specify below r consultant agree	equests for b ements, etc.):	ids and proposals, subcontrac		
	N/A				
		·			
Other doo	cuments and records (Specify belo	w):			
	N/A	,			
		· · · · · · · · · · · · · · · · · · ·			
		·			

REFERENCED TECHNICAL GUIDANCE FOR PROJECT ACTIVITIES

Reference the appropriate technical guidance which will apply to technical project activities performed during the course of this project. The primary reference is the NUS Superfund Division Operating Guidelines Manual (OGM). When applicable, other EPA accepted standard operating guidelines (SOG) and procedures (SOP) may be referenced.

Technical guidance must be specifically referenced. If portions of the OGM are referenced, indicate the OGM section and, if applicable, the subsection. Reference of EPA SOG's and SOP's must indicate the publication title, number and date.

If a technical project activity is not applicable indicate "NA". If a technical project activity is not provided, list it under "other" (see page 10 of 11) and reference applicable technical guidance.

Reference	Technical Project Activity
NA	Ambient Air Sampling (OVA, HNU, etc.)
ii/A	Ground-Water Sampling
N/A	Surface-Water Sampling
N/A	Soil/Sediment Sampling
N/A	Tap Water Sampling
N/A	Land Surveying
N/A	Electrical Resistivity Survey
N/A	Electromagnetic Survey
N/A	Magnetometer Survey
N/A	Metal Detection Survey
N/A	Ground Penetrating Radar Survey
N/A	Seismic Survey
N/A	Water Level Measurements
N/A	Perimeter Survey
N/A	Site Inspection
N/A	Soil Borings/Well Installation
N/A	Bedrock Fracture Analysis
N/A	Pump/Permeability Tests
N/A	Preparation of Water Table Maps
N/A	Preparation of Bedrock Contour Maps

	WPF 1/31/86
	Page 12 of 13
Work Plan No	1W- 52-4038-60.
Revision	0

REFERENCED TECHNICAL GUIDANCE FOR PROJECT ACTIVITIES (Cont'd)

Reference	Technical Project Activity
N/A	Determination of Ground-Water Flow
N/A	Decontamination Procedures
Others (list below):	
OGM 4.15	Preliminary Assessments
00-M 4.31	Organization of the Field Team
OGM 5.10	Organization of the Field Team Beneral Safety Guidlines Applicable to All Field Achiustic
	·
	· · · · · · · · · · · · · · · · · · ·

QA PROGRAM APPLICABILITY

The following portions of the NUS Superfund Division Quality Assurance Manual are applicable to the performance of specific work activities defined in TDD # 02-8604-22.

(/)	Number	Subject
<u> </u>	QAP 2.5	Work Plans
	QAP 3.1	Control of Remedial Design Activities
	QAP 3.2	Drawing Control
	QAP 3.3	Design Calculations
<u> </u>	QAP 4.1	Field Data Collection
	QAP 4.2	Data Reduction, Validation, and Reporting
	QAP 5.1	Preparation of Procurement Documents
	QAP 5.2	Subcontractor Quality Assurance Requirements
	QAP 6.1	Preparation of Instructions and Procedures
<u>x</u>	QAP 7.1	Identification of Controlled Evidentiary Documents
<u>x</u>	QAP 7.2	Issuance and Distribution of Controlled Documents
	QAP 7.3	Development, Documentation, Verification, and Retention of Software Programs
<u> </u>	QAP 7.4	Technical Reports
	QAP 8.1	Control of Subcontractor Procurement Activities
	QAP 8.2	Evaluation and Selection of Subcontractors
	QAP 9.1.F2	Chain of Custody
	QAP 9.2.F2	Sample Control
<u>:</u>	QAP 10.1	Analysis Techniques
<u>_x</u>	QAP 11.1	Offsite Reconnaissance
	QAP 11.2	Onsite Inspections
	QAP 12.1	Implementation of Measuring and Test Equipment Controls
	QAP 13.1	Packaging, Marking, Labeling, and Shipping of Samples from Hazardous-Waste Sites
<u> </u>	QAP 14.1	Nonconformance Reporting, Evaluation, and Disposition
<u> </u>	QAP 15.1	Implementation and Documentation of Corrective Actions
<u> x</u>	QAP 16.1	Storage and Retrieval of Quality Assurance Records and SFD Project Files
	QAP 17.4	Preparation for Audit
<u> </u>	QAP 17.6	Quality Notices

WPF
Work Plan No. <u>Da-8664-72</u> -W1
Revision

ATTACHMENT A

DDT

(Attach Copy of TDD)

1. COST CENTER:				2. NO. :		
F-2	1	FIT ZONE CONTRACT				
ACCOUNT NO.:	TECHNICAL	(סו	02-8604-22			
0400.01			<u>. </u>			
3. PRIORITY:	4. ESTIMATE OF TECHNICAL HOURS:	5. EPA SITE ID:	6. COMPLETION DA	TE: 7. REFERENCE INFO.:		
□ нібн	55	NYD044837086		YES XNO		
X MEDIUM	4A. ESTIMATE OF SUBCONTRACT COST:	5A. EPA SITE NAME:MIDLAND		ATTACHED		
	N/A	PROCESSING	5/31/86	PICK UP		
8. GENERAL TASK DESCRI		ESSING	<u> </u>			
		fork, Rockland Cour	nty			
	Preliminary /	Assessment				
			·			
9. SPECIFIC ELEMENTS:				10. INTERIM		
1. Conduct Fi	le Search Of U.S. EPA	A. State EPA. And/(r local	DEADLINES:5/07/86		
	And/Or Health Agency					
	Anay of Heat on Agency	11103				
	2. Review And Evaluate Available Information And Conduct Off-Site 5/16/86 Reconnaissance If Necessary					
3. Submit Four-Page Preliminary Assessment Report (Includes 5/31/86 EPA Form 2070-12)						
11. DESIRED REPORT FOR	M: FORMAL REPORT	LETTER REPO	ORT FOF	RMAL BRIEFING [
OTHER (SPECIFY):	·		<u>:</u>			
12 COMMENTS: O.	ontime Annual					
12. COMMENTS:Ov	ercime approved					
13. AUTHORIZING RPO:			Т	14. DATE:		
Diana Messina	(SIGNATURI	E)				
15. RECEIVED BY: ACCEPTED ACCEPTED WITH EXCEPTIONS REJECTED 16. DATE:						
Ronald M. Naman (CONTRACTOR RPM SIGNATURE)						

Sheet 1 Sheet 2 White — FITL Copy Canary — DPO Copy

Sheet 3 Sheet 4 Pink — Contracting Officer's Copy (Washington, D. C.) Goldenrod — Project Officer's Copy (Washington, D. C.)

WPF Work Plan No. 02-8604-22-W1 Revision

ATTACHMENT B

SAFETY PLAN

(Must have Identifying Control #)

AB-SSP 02/06/86

Page 1 of 2

Doc. No.: 02-2604-22-51

Ref. 62-8604-22-WI

(Work Plan #)

ABBREVIATED SITE SAFETY PLAN FOR OFF-SITE RECONNAISSANCE

SITE NAME: Midland Roce Sing	TDD NO: 02-8604-22
ADDRESS: Pomona, W.Y. Rockland	County
PURPOSE OF SITE VISIT: OSF-SITE recor	nussunce
PROPOSED DATE OF WORK: 05/16/86	
PROPOSED SITE INVESTIGATION TEAM: Individuals	will be listed in the field notebook.
SITE STATUS: Active Inactive	
SITE DESCRIPTION: Unithous	
SITE HISTORY: Un Kown	
PERIMETER ESTABLISHMENT: All work will be conducted areas.	cted off-site from public access
Perimeter identified?	
	•
MONITORING EQUIPMENT:	
HNU TLD Bad	dge
	on mini-alert
Victoreen Radiation Detecto	
PLAN PREPARATION:	
Prepared by: Josephson	
Approvals:	4
Regional Health & Safety Manager: Mull	Aneiding (515182)
Regional Project Manager:	(5/6/84)

AB-SSP 02/06/86

Page 2 of 2

Doc. No: 02 - 8604-22-51

EMERGENCY INFORMATION:

1	0	\sim	Δ	ī	D	FS	(1 1	D	CE.	ς.
п	_ \ /	٠	7	_	1			L J		.	

Ambulance (Name): Ramage Valley Ambulene,	Phone (914) 357 - 201/
Hospital (Name): NYACK Hospital	Phone 9141 358 358-6200
Police (Local or State): Clarkstown Police	Phone (914) 634-2400
Fire Dept. (Name & Volunteer?): Sainwalky Fire Co.	Phone (914) 356-4200 Fire Calls Only
Radio Channel:	
Nearest Phone:	

OFFICE RESOURCES:

Region II FIT Office	201-225-6160
Diana Messina-EPA RPO	201-321-6776 (office)
Ron Naman-RPM	201-873-0166 (home)
Rich Califano-ARPM	914-337-3423 (home)
Laurie Gneiding-RHSM	201-534-2907 (home)
Tom Centi-ZPMO	703-522-8802 (office)

EMERGENCY CONTACTS: (Medical and Health)

o Dr. David K. Parkinson (NUS Consulting Physicians - University of Pittsburgh) Dr. Hodgson

24 Hour Number

412-624-0127

Say that you are from NUS Corporation and that this is an emergency call. Nights and weekends you must give your name and number where the physician can call you back.

o Gary Smith (NUS Zone Health and Safety Manager)

Office		412-788-1080
Home		412-695-3667

o Regional Health Maintenance Program Gateway Health Services

Dr. Edward Holstein 201-225-5454

o Poison Information Center NJ 800-962-1253 NY 201-926-8005

DIRECTIONS TO HOSPITAL (Attach Map): At end of Quaker know make
a Right travel south on Middle town Road, Finds Pulsarden Parkway
at Bont 10. Travel South to New york State Throway Travel FAST
ON New York State true was to exit is NYAK Take exit Il to
North Midland, Travel north or N. Midland 5 blocks.

